Oil Field Environmental Incident Summary

Responsible Party: Oasis Petroleum

Well Operator: OASIS PETROLEUM NORTH AMERICA LLC

Well Name: ACHILLES 5301 41-12B

Field Name: BAKER Well File #: 22100

Date Incident: 9/28/2014 Time Incident: 09:30 Facility ID Number:

County: MCKENZIE Twp: 153 Rng: 101 Sec: 12 Qtr: SW SW

Location Description:

Submitted By: Todd Hanson Received By:

Contact Person: Todd Hanson

1001 FANNIN STE 1500 HOUSTON, TX 77002

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1 MileDistance Nearest Water Well:1 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike Reported to NRC: Unknown

Spilled Units Recovered Units Followup Units
Oil 5 Barrels 5 Barrels 5 barrels

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 3/23/2016 Clean Up Concluded: 10/5/2014

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

thief hatch will be fixed today, that was the main problem , the transfer pump will be fixed also to keep the tank levels down

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 9/29/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location within the diking according to the report. NDIC retains oversight.